NORTHSIDE

18 Mill Lane, Leeds LS6 2AB · 0113 496 0123 · service@example.com · example.com

JOB NO.

FFR-0142

Cold Room Service · example

30/10/2026

Site: Harbour Café

Engineer: Alex Morgan

Visit details

Site / Customer	Harbour Café (example)
Engineer	Alex Morgan
Visit date	2026-10-30
Equipment	Walk-in cold room · CR-01

Work carried out

Reported fault	Cold room warmer than usual during opening checks.
Findings	Dust restricted airflow through the condenser coil. Door seals and drain sound.
Work carried out	Cleaned condenser coil, checked fan operation and confirmed room temperature returned to 3.2°C.

Operating checks

Room temperature	3.2
Suction pressure	2.1

Final checks

Condenser coil clean	YES
Door seals sound	YES
Drain clear	YES

NORTHSIDE

18 Mill Lane, Leeds LS6 2AB · 0113 496 0123 · service@example.com · example.com

JOB NO.

FFR-0142

Cold Room Service · example

30/10/2026

Site: Harbour Café

Engineer: Alex Morgan

Visit photos

Condenser after cleaning



30/10/2026 09:42 · 53.80080, -1.54910 · captured in app

Open in maps

Customer sign-off

Customer signature

Print name

Print name

Print name